

<b>Final Inspection Housekeeping Room #603</b>					
<b>SI No:</b>	<b>Item</b>	<b>Status</b>	<b>Qty</b>	<b>Price</b>	<b>Total</b>
<b>Total</b>					<b>0.00</b>

<b>Final Inspection Engineering Room #603</b>					
<b>SI No:</b>	<b>Item</b>	<b>Status</b>	<b>Qty</b>	<b>Price</b>	<b>Total</b>
1	Maids bathroom WC tank crack	Damaged	1	800	800
<b>Total</b>					<b>800.00</b>

<b>Grand Total</b>					<b>800.00</b>
--------------------	--	--	--	--	---------------

Final Inspection Room #1503					
SI No:	Item	Status	Qty	Price	Total
1	Twin bedroom carpet	Heavy stain	1	466	465.79
2	Master bedroom bed skirting	Missing	1	300	300.00
<b>Total</b>					<b>765.79</b>

Final Inspection Engineering Room #1503					
SI No:	Item	Status	Qty	Price	Total
1	Entrance bathroom door	Damage	1	5000	5000
<b>Total</b>					<b>5,000.00</b>

<b>Grand Total</b>					<b>5,765.79</b>
--------------------	--	--	--	--	-----------------

<b>Final Inspection Housekeeping Room #1803</b>					
<b>SI No:</b>	<b>Item</b>	<b>Status</b>	<b>Qty</b>	<b>Price</b>	<b>Total</b>
1	Bathroom pedal dustbin	Missing	1		
2	Desk chair	Missing	2	#####	1047
3	Arm chair	Missing	1	1037	1037
4	Queen mattress	Damaged	1		
5	Twin mattress	Damaged	1		
<b>Total</b>					<b>2,083.79</b>

<b>Final Inspection Engineering Room #1803</b>					
<b>SI No:</b>	<b>Item</b>	<b>Status</b>	<b>Qty</b>	<b>Price</b>	<b>Total</b>
1	Master bathroom bathtub knob	Damaged	1		
<b>Total</b>					<b>0.00</b>

<b>Grand Total</b>					<b>2,083.79</b>
--------------------	--	--	--	--	-----------------

<b>Final Inspection Housekeeping Room #2703</b>					
<b>SI No:</b>	<b>Item</b>	<b>Status</b>	<b>Qty</b>	<b>Price</b>	<b>Total</b>
1	Twin room disk chair	Missing	1	523.40	675
2	Master room mattress protector	Missing	1		
3	Dressing chair	Missing	1	523.40	500
4	Mobilization charges				
<b>Total</b>					<b>1,175.00</b>

<b>Final Inspection Engineering Room #2703</b>					
<b>SI No:</b>	<b>Item</b>	<b>Status</b>	<b>QTY</b>	<b>Price</b>	<b>Total</b>
1	Twin bedroom Chandelier bulb cover	Missing	3		
2	Common Bathroom bidet tap nozzle	Missing	1		
3	Master bedroom TV LG remote	Missing	1		
4	Maids room door cylinder	Different	1		
5	Common bathroom bath tub stopper	Missing	1		
6	Common bathroom wash basin, floor drain cover, bidet stoppe	Missing	3		
7	Maids bathroom wash basin stopper	Missing	1		
<b>Total</b>					<b>0.00</b>

<b>Grand Total</b>					<b>1,175.00</b>
--------------------	--	--	--	--	-----------------